

Ways to fix the sensor.

Check to see if pressure lines have come off on the circuit board. Clear line goes to fill pressure sensor. Black line goes to drain pressure sensor.

Proper way to install hose on pressure sensor, Push the hose on to the sensor half way then put a drop of super glue on the sensor running on top of the hose to make them bond together.